

8/5/2014 Page 1 of 12



1675 Locust Street Red Bud, IL 62278 Phone: 618-282-8200 Fax: 618-282-8202

WARRANTY & TERMS

WARRANTY: 5 Year Limited Warranty on Thermoplastic coated elements. Ultra Play guarantees all items for one full year to be free of defects in workmanship or materials when installed and maintained properly. We agree to repair or replace, any items determined to be defective. Items specifically not covered by this warranty include vandalism, man made or natural disasters, lack of maintenance, normal weathering or wear and tear due to public abuse.

Damages or loss in transit is the responsibility of the carrier, whether visible or concealed. It is the responsibility of the recipient to assure that the order is received complete. Before signing the delivery receipt, inspect the shipment immediately and completely. Note any damages or shortages on the bill of lading. Damage reports must be filed within 10 days. Ultra Play is NOT responsible for damages or loss in transit. Title to all goods passes to the customer at the time of shipment. Ultra Play will assist in filing claims if the freight arrangements were made by Ultra Play at your request.

CANCELLATIONS AND RETURNS: Cancellations are only accepted with approval of Ultra Play. No merchandise shall be returned without a Return Goods Authorization number which is issued by customer service. Any authorized merchandise must be carefully packed and received in saleable condition. A restocking charge of up to 25% will be applied to all returned goods when the error is not the fault of Ultra Play. All returns must be shipped freight prepaid.

8/5/2014 Page 2 of 12



SAFETY WARNINGS & EQUIPMENT INSPECTION

- Owners and installers please note these safety warnings and make use of this checklist on a regular basis.
- Follow installation instructions when erecting equipment.
- Ground surfaces around equipment should be restored as needed. Concrete footings should never be exposed. Surface depth should comply with ASTM and CPSC specifications.
- Check for and repair damage caused by wear or vandalism, a major factor in injury causing situations.
- All protruding bolts should be covered or cut off and finished smooth. Sharp edges on pipes should be capped or removed. Check for bent, broken, or severly worn pipe, and replace.
- All equipment should be free of rust and repainted whenever necessary to deter rusting.
- We provide our customers with layout sheets and installation instructions. Please keep on file the specifications sheet that contains the listing of every part used.
- Never add components not intended for use with this product.
- Regular maintenance is necessary in this and all park and recreational equipment to insure the safety of the user.
- Note: Proper maintenance of equipment requires regular tightening of all bolts, nuts, and setscrews.
- Note: Regular checking of all parts, castings, etc. should be made. If a part is broken or worn, it should be replaced immediatly.
- Check to be sure all fittings are tight and that bars and pipes do not move.
- Replace all worn S-hooks. S-hooks must be completely closed. Failure to close S-hooks can result in serious injury to the user.
 NEVER reuse S-hooks.
- Test for free movement of swing hanger and other moving attached parts.
- Check for worn chains and replace them.
- A soft resilient surface should be placed under all swings extending at least twice the height of the top rail both front and back.

8/5/2014 Page 3 of 12

HARDWARE



5/16" X 1" Machine Bolt



5/16" Washer




5/16" Kep Nut





800-45-ULTRA www.ultra-site.com


8/5/2014 Page 4 of 12

TOOLS REQUIRED









ultra site.

800-45-ULTRA www.ultra-site.com

8/5/2014 Page 5 of 12

ULTRA SITE PRODUCT SPECIFICATIONS

358-OV 46" PORTABLE TABLE WITH 4 SEATS

Top & Seats: 11 gauge die formed angle frame 1"x1-7/8". 3/4" #9 steel expanded metal. 7 gauge x 1-1/2" flat bar center support and mounting bracket understructure. Top is additionally supported to the corners with 7 gauge x 1-1/2" flat bar. Electrically MIG welded.

Coating: Oven fused functionalized polyethylene copolymer-based thermoplastic. Fluidized bed coating application with superior mechanical performance, impact resistance and UV-stability.

Frame: 1-5/8" O.D. x 14 gauge pre-galvanized structural steel tubing. Brace attachment points are 1-1/2"x2"x3/16" steel flat bar. Cross braces 1" O.D. x 16 gauge pre-galvanized structural steel tubing. Top is attached with 7 gauge 2"x2" die formed angle. Seat mounting points are 7 gauge x 1-1/2" die stamped steel flat bar. Legs are bent over a mandrel through the bend radius producing a wrinkle free bend. All electrically MIG welded.

Frame Coating: Electrostatic powder coated application oven cured.

Hardware: All stainless steel hardware fasteners.

Dimensions: Top is 46" square x 30-1/4" high. Seats are 12" wide x 36" long x 18" high. Outside to outside dimensions of 4 seat table is 77-3/4" square.



www.ultra-site.com

8/5/2014 Page 6 of 12

800-45-ULTRA

COMPONENTS DESCRIPTION ITEM NO. PartNo QTY T-OV46-T 46" Octagon Expanded Top 1 2 P-V358-R 358 Vinyl Leg R 4 3 P-V358-L 358 Vinyl Leg L 4 P-01-04-0121 358 Extension Tab 4 T-V36-S 3' Expanded Seat 5 4 6 33-02-0007 5/16" SS Washer 72 7 33-05-0029 5/16" x 1" Machine Bolt (SS) 36 8 33-03-0012 5/16" Kep Nut (SS) 36



P-01-04-0122

358 Crossbrace w/ Umbrella Tube

800-45-ULTRA

www.ultra-site.com

8/5/2014 Page 7 of 12


STEP 1 Attach the Extension Tabs to the 46" Octagon Top using specified hardware. 0 (7)ultra site

Page 8 of 12 8/5/2014

www.ultra-site.com

800-45-ULTRA

STEP 2




Attach the 358 Legs to the Extension Tabs using specified hardware.



800-45-ULTRA www.ultra-site.com

8/5/2014 Page 9 of 12

STEP 3



Attach the Crossbrace between the table legs as shown using specified hardware.



800-45-ULTRA www.ultra-site.com

8/5/2014 Page 10 of 12

STEP 4




Attach the 3' Seats to the 358 Legs using specified hardware.



800-45-ULTRA

www.ultra-site.com

8/5/2014 Page 11 of 12



8/5/2014 Page 12 of 12